


1978-1983 chrome plate Receiver

Must Send to Service Station
EXPLODED VIEW, PARTS AND PRICE LIST
Model 2200 Phase I




This parts and price list is intended to be an informational guide in ordering Crosman parts. It is not instructional material and we therefore assume no responsibility for those who use same without proper factory training.

SEAL KIT

2200H021 5.40
 760-140 .45
 130-036 .25
 TOTAL 6.10

*Hand Part to L.H. Receiver
 Top of Valve Body
 R.H. Service Sleeve*



Note
 If you order and receive 2200E017 Valve Body
 or 2200H021 Complete Valve Assy. you do not have
 to use 2200-037 Breech Gasket Sleeve.

Parts 766-022, 023, 024, 2200-001
 R.H. Receiver and 2100-016 should
 be assembled together as one unit
 before replacing L.H. Receiver
 2200-001 on R.H. Receiver 2100-002.